Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW4039/1
Work Order Type: Weatherization
Audit Name: Audit (74)

CLIEN	T INF	ORM	ATION

Client Name: Address:
Client ID: 12012NW4039

Alt. Client ID:

AGENCY INFORMATION

Agency: N.W.T.N.E.D.C

Agency Phone: (731) 364-3228

Address:

Fax:

dresden, TN Email Address:

Company Name & License Number: _	
Contractor's Signature:	

COMMENT

Client Name: Client ID: 12012NW4039 Alt. Client ID: Work Order (Bid Form)
Work Order Name: WO/12012NW4039/1

DOE Weatherization Assistant Version 8.5.0 Page 1 of 6

Report Run On: 5/23/2010

Measures

	Measure 1 Infilt	ration Redctn			Componen	ts			Inspected
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1					
		pack & foam kitchen plumbing							
(Other Detail						1		
				Measur	e Sub Total:] :	Sub Total:	
	Field Notes:								
	Measure 2 DWI	l Tank Insulation			Componen	ts			Inspected
	Measure 2 DWH	H Tank Insulation			Componen	ts			Inspected
		I Tank Insulation			Componen Estimated			Actual	Inspected
C		H Tank Insulation Description / Comment	Units	Qty	•		Qty		Inspected
<i>C</i>	Comment		<i>Units</i> Each		Estimated	<u> </u>	Qty	Actual	
# 1	Comment Material / Labor Hot Water	Description / Comment		Qty	Estimated	<u> </u>	Qty	Actual	
C # 1	Material / Labor Hot Water Equipment	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	<u> </u>		Actual	
C # 1	Material / Labor Hot Water Equipment Labor Other Detail	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
C # 1	Material / Labor Hot Water Equipment Labor Other Detail	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 3 DV Comment	VH Pipe Insulation			Componen				Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail						1		
			Measur	e Sub Total:]]	Sub Total:	
Field Notes:						-		
	eplace A/C			Componen	<i>t</i> s 1		ı	Inspected
Measure 4 Re Comment	place A/C			Componen Estimated			Actual	Inspected
	eplace A/C Description / Comment	Units	Qty	•		Qty		Inspected
Comment # Material / Labor		<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Cooling Equipment	Description / Comment			Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Cooling Equipment	Description / Comment Window A/C -	Each	1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Cooling Equipment 2 Labor	Description / Comment Window A/C -	Each	1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Cooling Equipment 2 Labor	Description / Comment Window A/C -	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / Labor 1 Cooling Equipment 2 Labor	Description / Comment Window A/C -	Each	1	Estimated	<u> </u>		Actual	
# Material / Labor 1 Cooling Equipment 2 Labor	Description / Comment Window A/C -	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / Labor 1 Cooling Equipment 2 Labor Other Detail	Description / Comment Window A/C -	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 5 CO I Comment	Monitor is Needed			Componen	ts			Inspecte
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	mproper Venting (Cloth	nes Dryer)	Componen	ts			Inspecte
	mproper Venting (Cloth	nes Dryer)	Componen Estimated			Actual	Inspecte
Comment	mproper Venting (Cloth Description / Comment	nes Dryer	Qty	•		Qty		Inspecte
Comment # Material / Labor	Description / Comment	-		Estimated	1	Qty	Actual	
# Material / Labor Health and Safety Items	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
# Material / Labor Health and Safety Items	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
# Material / Labor Health and Safety Items Labor	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
# Material / Labor Health and Safety Items Labor	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
# Material / Labor Health and Safety Items Labor	Description / Comment Equipment	Units Each Hour	Qty 1	Estimated	1		Actual	
 Comment # Material / Labor 1 Health and Safety Items 2 Labor 	Description / Comment Equipment	Units Each Hour	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor 1 Health and Safety Items 2 Labor Other Detail	Description / Comment Equipment	Units Each Hour	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	

Report Run On: 5/23/2010

	Other Venting Related F ating System)	Problems		Componen	ts			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Equipment	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 8 Smo	oke Detector is Needed			Componen				Inspected
Comment		Units	Ofv	Estimated	<u>'</u>	Ofv	Actual	
Comment	Description / Comment	<i>Units</i> Each	Qty 1	•		Qty		Inspected Total
Comment# Material / Labor1 Health and Safety	Description / Comment			Estimated	<u>'</u>	Qty	Actual	
Comment# Material / Labor1 Health and Safety Items	Description / Comment Smoke detector	Each	1	Estimated	<u>'</u>	Qty	Actual	
Comment# Material / Labor1 Health and Safety Items2 Labor	Description / Comment Smoke detector	Each	1	Estimated	<u>'</u>	Qty	Actual	
Comment# Material / Labor1 Health and Safety Items2 Labor	Description / Comment Smoke detector	Each	1	Estimated	<u>'</u>	Qty	Actual	
Comment# Material / Labor1 Health and Safety Items2 Labor	Description / Comment Smoke detector	Each Hour	1	Estimated	<u>'</u>		Actual	

Report Run On: 5/23/2010

	Measure 9 gene	ral repair			Componer	its			Inspected
C	Comment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	repair 2x5 in kitchen area	SqFt						
2	Construction Materials/Hardwar e	repair 2x4 area in ceiling where hot water heater room	SqFt						
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
			Work Or	rder Gra	nd Total:		Gran	d Total:	